


Project-based activities process map: measurement and verification

This process map shows the steps businesses must follow to receive Victorian energy efficiency certificates (VEECs) using the measurement and verification pathway.

We may elect to do a site inspection at certain stages of this process.

While this process map shows the scoping plan and project plan being completed separately, you can opt to submit them to us at the same time. However, you will still need to wait for the scoping plan to be approved prior to starting work on site.

For all documents and forms related to this process, visit www.esc.vic.gov.au/pba.



¹ The baseline and impact measurements must be completed before the end of the stage indicated. These measurements may take up to 24 months. In some special cases, the baseline can be measured after the work is completed. Baseline measurements are not required for SMM4 and SMM5.

² Please refer to our guidance documents for more information on reporting and VEEC creation cycles.

* You can start undertaking work on site before this stage is completed.

■ Indicates something you must do.

◆ Indicates a milestone you must complete.

● Indicates something the commission must do.